

INSPECTION REPORT REVIEW
POTENTIAL HAZARDOUS WASTE SITE

SITE NAME : Precision National Corp

LOCATION : Waco, TX

SITE NUMBER: TXD056363708

SURVEY DATE: ___/___/___ INSPECTED BY: STATE FIT TAT OTHER: SIP 8/18/95 E+E

LABORATORY : ___CLP ___EPA ___OTHER___

RECEIVED FROM: Betty Williamson

DATE RECEIVED: 9/17/95

SAMPLE TYPE(s): None

SOIL	SURFACE WATER	GROUND WATER	DRINKING WATER
off / on -site	off / on -site	off / on -site	off / on -site

CONTAMINANT(s): Organics Inorganics Radionuclides Microbiological

FOLLOW UP (Y/N):

<u>N</u> (Re)Sampling Requested	<u>N</u> Locate Drinking Water Sources
<u>N</u> Further Action is URGENT	<u>N</u> Keep Site Active ("N"=No Further Action)
	<u>X</u> Concur with Report Recommendations

SUMMARY: This is a review of an SIP report for an active chromium facility and machine shop at which soil samples indicate the presence of chromium, copper, mercury and lead.

Ground water is not used within the target distance.

Surface water usage in the pathway is not given.

Information is insufficient to determine threat to drinking water although it appears minimal.

The SF recommendation is No Further Remedial Action Planned under Superfund. Concur with referral to the TNRCC for further appropriate action.

RECOMMENDATION: None

Concurrence:

AP ___/___/___

Neil H. Blum
ENGINEER/REVIEWER

1/25/95

8/12/95

90067063



T378-001-03